

**December 2019 MSCID AMA Service Report**

Zone Name	Asset													
	Broken Glass	graffiti removal	Illegal Dumping	Landscape services	Litter	maintenance Properties	Maintenance Service - Bus	Maintenance Service - Daily	other request	poster removal	snow-ice service	Sweeping	Trash Can Emptied	Total
2800 E	0	0	0	0	4	0	0	0	0	0	0	0	0	4
2800 W	0	0	0	0	3	0	0	2	0	0	0	0	0	5
2900 E	0	0	0	0	12	0	0	15	0	0	2	7	7	43
2900 W	0	0	0	0	11	1	0	16	0	0	2	8	10	48
3000 E	0	0	0	0	17	0	0	16	0	0	2	7	8	50
3000 W	0	0	0	0	18	0	0	21	0	0	2	12	11	64
3100 E	0	1	0	0	46	0	0	17	0	0	3	18	18	103
3100 W	0	0	1	0	17	1	20	19	0	0	4	29	17	108
3200 E	0	0	1	0	53	1	0	19	0	0	4	86	9	173
3200 W	0	0	0	0	0	17	15	19	0	0	3	12	10	76
3300 E	0	0	0	0	26	0	0	22	0	0	3	0	0	51
3300 W	0	0	0	0	0	0	0	20	0	0	4	5	0	29
3400 E	0	0	0	0	61	2	0	21	0	0	4	23	10	121
3400 W	0	0	1	0	30	2	0	22	0	0	5	17	0	77
3500 E	0	1	0	0	61	0	0	20	0	0	3	26	28	139
3500 W	0	0	3	1	2	0	2	18	5	0	7	48	9	95
3600 E	0	0	0	0	26	0	0	1	0	0	3	13	8	51
3600 W	0	0	0	1	2	0	0	3	5	0	9	31	9	60
3700 E	0	0	0	0	27	0	0	1	0	0	4	8	0	40
3700 W	0	0	0	1	28	0	0	3	1	0	7	21	9	70
3800 E	0	0	1	0	52	0	0	1	2	0	3	10	9	78
3800 W	1	0	0	1	36	0	0	1	0	0	6	26	0	71
3900 E	1	2	1	6	57	0	0	19	3	1	13	35	38	176
3900 W	0	2	0	5	52	0	0	1	0	1	16	70	16	163
4000 E	0	0	0	1	36	0	0	17	0	0	5	38	19	116
4000 W	0	0	0	0	33	0	0	19	0	0	5	21	8	86
4100 E	0	0	0	1	0	0	0	19	0	0	2	37	9	68
4100 W	0	0	0	0	0	0	0	18	0	0	3	32	0	53
4200 E	0	0	0	0	0	0	0	17	0	0	2	6	0	25
4200 W	0	0	0	0	0	0	0	18	0	0	2	8	0	28
4300 E	0	1	0	5	0	0	0	18	0	1	2	42	56	125
4300 W	0	0	0	1	0	0	0	17	0	0	4	26	8	56
4400 E	0	0	0	0	0	0	0	17	0	0	3	24	26	70
4400 W	0	0	0	0	0	0	0	18	0	0	2	16	0	36
4500 E	0	0	0	0	0	0	0	17	0	0	0	19	0	36
4500 W	0	0	0	0	0	0	0	16	0	0	1	19	9	45
4600 E	0	0	0	0	0	0	0	17	0	0	0	10	0	27
<b>Total</b>	<b>2</b>	<b>7</b>	<b>8</b>	<b>23</b>	<b>710</b>	<b>24</b>	<b>37</b>	<b>525</b>	<b>16</b>	<b>3</b>	<b>140</b>	<b>810</b>	<b>361</b>	<b>2666</b>