

May 2020 MSCID AMA Service Report

Zone Name	Asset									
	graffiti removal	Illegal Dumping	Landscape services	Litter	Maintenance Service - Bus Shelter/ Stop	Maintenance Service - Daily Routine	other request	Sweeping	Trash Can Emptied	Total
2700 E	0	0	0	0	0	2	0	0	0	2
2800 E	0	0	0	0	0	3	0	0	0	3
2800 W	0	0	0	2	0	1	0	0	0	3
2900 E	0	0	0	8	0	13	0	0	9	30
2900 W	0	0	0	6	0	13	0	0	10	29
3000 E	0	0	0	18	0	16	0	0	9	43
3000 W	0	0	0	16	0	19	2	3	9	49
3100 E	0	0	0	41	0	17	0	0	19	77
3100 W	0	2	2	18	17	17	4	6	17	83
3200 E	1	1	0	44	0	17	0	1	9	73
3200 W	0	0	0	17	14	17	2	5	9	64
3300 E	0	0	0	24	0	17	0	0	0	41
3300 W	0	0	0	0	0	17	0	3	0	20
3400 E	0	1	1	59	0	19	0	0	9	89
3400 W	0	0	1	27	0	17	2	4	0	51
3500 E	0	0	2	39	0	18	0	0	26	85
3500 W	0	1	1	0	0	12	6	14	9	43
3600 E	0	0	1	14	0	1	0	0	9	25
3600 W	0	0	3	0	0	1	5	10	9	28
3700 E	0	0	1	13	0	1	0	0	0	15
3700 W	1	0	2	15	0	1	0	0	9	28
3800 E	0	0	1	15	0	1	0	0	9	26
3800 W	0	0	1	15	0	1	0	0	0	17
3900 E	3	4	4	21	0	17	4	0	40	93
3900 W	0	0	1	18	0	1	0	0	18	38
4000 E	0	0	2	16	0	17	0	0	18	53
4000 W	0	0	1	15	0	18	0	0	9	43
4100 E	0	0	1	8	0	16	0	0	9	34
4100 W	0	0	0	8	0	18	0	0	0	26
4200 E	0	0	0	6	0	17	0	0	0	23
4200 W	0	0	0	6	0	20	0	0	0	26
4300 E	1	0	3	9	0	17	2	0	55	87
4300 W	0	0	1	0	0	19	2	5	10	37
4400 E	0	0	0	9	0	16	1	0	27	53
4400 W	0	0	0	8	0	17	0	0	0	25
4500 E	0	0	0	5	0	18	0	0	1	24
4500 W	0	0	0	5	0	18	0	0	9	32
4600 E	0	0	0	3	0	18	0	0	0	21
Total	6	9	29	511	31	488	30	51	367	1539